

# **Htek IP phones Release Notes of Version**

# Introduction:

# **❖** Product Model:

UC926/UC926E/UC924/UC924E/UC912E/UC923/UC902/UC903/UC912/UC9 12G/UC901/UC862/UC842/UC860P/840P/806P/UC806G/UC806T/UC804P/ UC804G/UC804T/803P/802P/UC802T

## **\*** Firmware Version:

UC8XX/UC9XX--2.0.4.8.9

#### Release Date:

2020.11.11


**Version: 2.0.4.8.9** 

#### **New Add Features**

- CDP, LLDP, and DHCP VLAN new mechanisms are incorporated
- Jitter Buffer overflow prevention related changes Check and integration
- Ti3100 synchronous operation of business agreement related changes Check and join
- Add Password Dial

Web -> Setting -> Preference ;p25045:0-off,1-on,default is off





#### **Delete Features**

• N/A

## **Improve Features**

• N/A

#### Fix issue

- No RPS assignment after option66 assignment fails
- Headset Loses Control After Missed Call
- [SRTP] "TLS registration + SRTP" for a call, the DUT hears a stutter
- Copyright © 2005-2019 All Rights Reserved Update 2005-2020
- Through the forward configured by Dsskey, there is a problem with turning on and off
- Headset turns off on incoming call
- Smartlifetech: BLIND transfer process is incorrect
- Https chunk error
- After Outbound Proxy DOWN, switching to Backup Outbound Proxy is abnormal
- When manually switching Transport Type, the unbinding is not done correctly
- On Incoming Call, call cannot be Rejected when using the CTI of the 3CX Windows App
- Queue Missed Calls leave Missed Call on display
- Outbound calls the caller on the htek handset (calls to external parties) sound extremely quiet to the receiving end.



- The broadcast number is too long, and the number in the history record shows overlap
- Fix UC903 headset failure