

## Htek IP phones Release Notes of Version

### Introduction:

#### ❖ Product Model:

UC926/UC926E/UC924/UC924E/UC912E/UC923/UC902/UC903/UC912/UC912G/UC901/UC862/UC842/UC860P/840P/806P/UC806G/UC806T/UC804P/UC804G/UC804T/803P/802P/UC802T

#### ❖ Firmware Version:

UC8XX/UC9XX--2.0.4.8.10

#### ❖ Release Date:

2021.02.07

### Version: 2.0.4.8.10

#### New Add Features

- Improve sound quality
- SPT-641:Overwriting user made setting
- HTTPS/TLS add specified new algorithm —— ECDHE-RSA-AES256-GCM-SHA384;ECDHE-RSA-AES128-GCM-SHA256
- After the user has modified the ringtone on the web page or LCD, it is not allowed to modify the corresponding ringtone P value by assigning cfgmac.xml

#### Delete Features

- N/A

## Improve Features

- N/A

## Fix issue


- Fix some problems with TLS registration.
- Fixed TLS registration dropped after a period of inactivity
- Repair accounts are registered, but the line on UC46 shows that the registration failed
- Fix TLS registration failure
- Fix Profile3 Fallback Interval display error
- Fix black and white LCD display problem
- Repair the non-idle state to click the hands-free button, the hands-free light does not turn on
- Fix the phone has two incoming calls at the same time, switch to the second one and click the hands-free button to hang up the second incoming call
- Fix the incomplete loading of the phone switching wallpaper
- Fix 902S background cannot be loaded
- Fixed the failure to upgrade the MTK expansion board of the phone

## Version: 2.0.4.8.9

## New Add Features

- CDP, LLDP, and DHCP VLAN new mechanisms are incorporated
- Jitter Buffer overflow prevention related changes Check and integration
- Ti3100 synchronous operation of business agreement related changes Check and join
- Add Password Dial

Web -> Setting -> Preference ;p25045:0-off,1-on,default is off



The screenshot shows a configuration dialog box with the following elements:

- Password Dial Open:** A radio button group with "On" (unselected) and "Off" (selected) options.
- Password Dial Prefix:** An empty text input field.
- Password Dial Length:** A text input field containing the value "0".
- Buttons:** "SaveSet" and "Cancel" buttons at the bottom.

## Delete Features

- N/A

## Improve Features

- N/A

## Fix issue

- No RPS assignment after option66 assignment fails
- Headset Loses Control After Missed Call
- [SRTP] "TLS registration + SRTP" for a call, the DUT hears a stutter
- Copyright © 2005-2019 All Rights Reserved Update 2005-2020
- Through the forward configured by Dsskey, there is a problem with turning on and off
- Headset turns off on incoming call
- Smartlifetech: BLIND transfer process is incorrect
- Https chunk error
- After Outbound Proxy DOWN, switching to Backup Outbound Proxy is abnormal
- When manually switching Transport Type, the unbinding is not done correctly
- On Incoming Call, call cannot be Rejected when using the CTI of the 3CX Windows App
- Queue Missed Calls leave Missed Call on display
- Outbound calls the caller on the htek handset (calls to external parties) sound extremely quiet to the receiving end.

- The broadcast number is too long, and the number in the history record shows overlap
- Fix UC903 headset failure

Htek