

## Htek IP phones Release Notes of Version

### Introduction:

❖ **Product Model:**

UC926(E)/UC924(E)/UC923/UC921(G)/UC912(E/G)/UC903/UC902(S)

❖ **Firmware Version:**

UC9XX--2.0.4.8.12

❖ **Release Date:**

2021.09.07

### **Version: 2.0.4.8.12**

#### **New Add Features**

- HTTPS/TLS add specified new algorithm
  - TLS\_ECDHE\_ECDSA\_WITH\_AES\_128\_CBC\_SHA256 0xC023
  - TLS\_ECDHE\_ECDSA\_WITH\_AES\_256\_CBC\_SHA384 0xC024
- List of newly added certificates
  - [www.ssl.com](http://www.ssl.com)
  - SSL.com EV SSL Intermediate CA ECC R2
  - SSL.com EV Root Certification Authority ECC

#### **Delete Features**

- N/A

## Improve Features

- N/A

## Fix issue

- Fix SNMP not working

## Version: 2.0.4.8.11

## New Add Features

- HTTPS/TLS add specified new algorithm
  - TLS\_ECDHE\_RSA\_WITH\_AES\_128\_CBC\_SHA 0xC013
  - TLS\_ECDHE\_RSA\_WITH\_AES\_256\_CBC\_SHA 0xC014
  - TLS\_ECDHE\_RSA\_WITH\_AES\_128\_CBC\_SHA256 0xC027
  - TLS\_ECDHE\_RSA\_WITH\_AES\_256\_CBC\_SHA384 0xC028
- 3CX assigned and registered DNS policy changes

## Delete Features

- N/A

## Improve Features

- N/A

## Fix issue

- Fix unable enter "+" char to wifi password
- When receiving a NOTIFY from PNP, the phone replied with a garbage string in the 200 OK

## Version: 2.0.4.8.10

## New Add Features

- Improve sound quality

- SPT-641:Overwriting user made setting
- HTTPS/TLS add specified new algorithm —— ECDHE-RSA-AES256-GCM-SHA384;ECDHE-RSA-AES128-GCM-SHA256
- After the user has modified the ringtone on the web page or LCD, it is not allowed to modify the corresponding ringtone P value by assigning cfgmac.xml

## Delete Features

- N/A

## Improve Features

- N/A

## Fix issue


- Fix some problems with TLS registration.
- Fixed TLS registration dropped after a period of inactivity
- Repair accounts are registered, but the line on UC46 shows that the registration failed
- Fix TLS registration failure
- Fix Profile3 Fallback Interval display error
- Fix black and white LCD display problem
- Repair the non-idle state to click the hands-free button, the hands-free light does not turn on
- Fix the phone has two incoming calls at the same time, switch to the second one and click the hands-free button to hang up the second incoming call
- Fix the incomplete loading of the phone switching wallpaper
- Fix 902S background cannot be loaded
- Fixed the failure to upgrade the MTK expansion board of the phone

**Version: 2.0.4.8.9**

## New Add Features

- CDP, LLDP, and DHCP VLAN new mechanisms are incorporated
- Jitter Buffer overflow prevention related changes Check and integration
- Ti3100 synchronous operation of business agreement related changes Check and join
- Add Password Dial

Web -> Setting -> Preference ;p25045:0-off,1-on,default is off



The screenshot shows a configuration window for 'Password Dial'. It includes three input fields: 'Password Dial Open' with radio buttons for 'On' and 'Off' (where 'Off' is selected), 'Password Dial Prefix' with an empty text box, and 'Password Dila Length' with a text box containing '0'. At the bottom, there are two buttons: 'SaveSet' and 'Cancel'.

## Delete Features

- N/A

## Improve Features

- N/A

## Fix issue

- No RPS assignment after option66 assignment fails
- Headset Loses Control After Missed Call
- [SRTP] "TLS registration + SRTP" for a call, the DUT hears a stutter
- Copyright © 2005-2019 All Rights Reserved Update 2005-2020
- Through the forward configured by Dsskey, there is a problem with turning on and off
- Headset turns off on incoming call
- Smartlifetek: BLIND transfer process is incorrect
- Htpps chunk error
- After Outbound Proxy DOWN, switching to Backup Outbound Proxy is abnormal

- When manually switching Transport Type, the unbinding is not done correctly
- On Incoming Call, call cannot be Rejected when using the CTI of the 3CX Windows App
- Queue Missed Calls leave Missed Call on display
- Outbound calls the caller on the htek handset (calls to external parties) sound extremely quiet to the receiving end.
- The broadcast number is too long, and the number in the history record shows overlap
- Fix UC903 headset failure

Htek