

## Htek IP phones Release Notes of Version

### Introduction:

#### ❖ Product Model:

UC926/UC926E/UC924/UC924E/UC923/UC912/UC903/UC902/UC503/UC503G/UC505/UC507/UC921G

#### ❖ Firmware Version:

UC9XX--2.21.4.6.26

UC5XX--2.21.4.6.26

#### ❖ Release Date:

2020.09.02

### Version: 2.21.4.6.26

#### New Add Features

- N/A

#### Delete Features

- N/A

#### Improve Features

- N/A

#### Fix issue

- Fix the issue that handset have very tinny sound.
- Fix the issue that UC507 cannot connect to MTK expansion .

- Fix the issue that Phones not getting LAN IP address on first boot

## **Version: 2.21.4.6.25**

### **New Add Features**

- N/A

### **Delete Features**

- N/A

### **Improve Features**

- N/A

### **Fix issue**

- Fix the issue that fallback interval in conjunction with NAPTR.

## **Version: 2.21.4.6.24**

### **New Add Features**

- N/A

### **Delete Features**

- N/A

### **Improve Features**

- N/A

### **Fix issue**

- Fix the issue that Calls dropping mid call([SUPPORT-402](#)).
- Fix the issue that Phone not registering using TLS([SUPPORT-218](#)).
- Fix the issue that Subscribe and INVITE not follow Register(DNS mode:SRV).
- Fix the issue that phone talks with the handset. Press Softkey2 to hold the call and then hang up the handset. The call is directly disconnected and does not switch to the Speaker state.

## Version: 2.21.4.6.23

### New Add Features

- N/A

### Delete Features

- N/A

### Improve Features

- N/A

### Fix issue

- Fix the issue that Line key getting renamed on incoming call([SUPPORT-387](#)).
- Fix the issue that BLF for SCA/SLA Line disappearing when put on hold after taking a call on second line([SUPPORT-135](#)).
- Fix the issue that phone can not answer the call when phone pressing Linekey.

## Version: 2.21.4.6.22

### New Add Features

- N/A

### Delete Features

- N/A

### Improve Features

- N/A

### Fix issue

- Fix the issue that the phone register failed when DNS Mode is set to SRV.

## Version: 2.21.4.6.21

## **New Add Features**

- N/A

## **Delete Features**

- N/A

## **Improve Features**

- N/A

## **Fix issue**

- TimeStamp is abnormal, sound is stuck.
- Use Outbound, phone TCP, TLS registration will not switch Server.

